



August 13, 2004

Mr. Robert R. Broyles
Superfund Division (6SF-RC)
U.S. EPA Region 6
1445 Ross Avenue
Dallas, TX 75202-2733

Re: Letter Dated August 03, 2004
Oil Spill in Cameron Parish, Louisiana on or about April 03, 2004
NRC Report No: 717825

Dear Mr. Broyles

In compliance with your request, the following information has been provided:

1. A report regarding the spill of crude oil into a water body which occurred on or about April 03, 2004. **See attached Uniform Hazardous Material Reporting Form.**
2. The amount of ~~product~~ spilled (in either barrels or gallons). **The amount reported is 1 to 1.5 bbls. See attached Uniform Hazardous Material Reporting Form.**
3. Duration of the spill event. **The spill occurred on April 03, 2004 at approximately 11:00am and was secured at approximately 12:00pm.**
4. The cause of the spill. **There was a hole in the flow line.**
5. Name the immediate receiving ditch, creek, stream, river, lake, arroyo, swale, etc. if known. **Immediate ditch is located East of Hwy 27 and South of Gulfport's gravel lease road.**
 - A. Also include the names of all downstream receiving waters that the spill affected. **There were no downstream receiving waters that the spill affected.**
 - B. Additionally, list all downstream receiving water bodies to the first major river or lake, regardless of whether or not the spill affected the water bodies. **The first major lake would be the Calcasien Lake; though the spill could not possibly affect this body of water.**

9491437



6. Site location map. **Site location map with facilities has been provided and is attached.**
7. Drawing of the site showing locations of the facilities. **Facilities have been included in site location map.**
8. Sketch of the spill site showing extent of the spill. **Sketch of spill site has been provided and is attached.**
9. Photographs of the spill and the spill site both before and after cleanup. **Photographs of the before spill site are not available though two photographs of the after spill site have been provided and are attached.**

All requests have been provided to the best of our ability. If we can further assist you, please contact Jessi Garrett at 405-848-8807 ext 122.

Respectfully,



Mike Liddell
Chief Executive Officer

BAO

Uniform Hazardous Materials Reporting Form

State Police Report # 717825

Incident # 04-02066

Date _____ Time _____

Courtesy Call () Reportable (x) Parish Cameron Notified _____
 Occurred 04/03/04 11:00 AM
 Caller's Name Louie Paul Gary A Class Operator Secured 04/03/04 12:00 PM

Caller's Employer Gulfport Energy Corporation

Caller's Phone # (337) 762-3388

Incident Location East Hackberry Field, Hackberry 10-W 12-S 12
 City Range Township Section

Company Gulfport Energy Corporation 561 North Main Hackberry, Louisiana 70645

Chemical Involved Crude Oil Address _____ Qty. 1.5 bbl (est) RQ _____

Hazard Class 3 ID 1267 EHS () Solid () Liquid (x) Gas ()

Did material go offsite? Yes X No _____ Release to: Land (x) Water (x) Air ()

Any off-site protective action? Yes _____ No X Road Closure () Shelter () Evacuation ()

Wind Direction South Fire Y () N (x)
 Wind Speed 6 - 8 MPH Injuries Y () N (x)
 Temperature 75 degrees Fatalities Y () N (x)
 Precipitation: None X Rain _____ Other _____

Details:

A flow line leak was discovered by Operator Louie Paul Gary at approximately 11:00 A.M. April 3, 04 on the M.P. Erwin Lease owned by Gulfport Energy Corp. An estimated 1 to 1.5 bbls of crude oil was released into the water and marshy area near Hwy. 27 South on the East side. Upon discovery of the leak, Mr. Gary took immediate action to begin the process of shutting in the source of the leak and containment. Once he had the field shut in and completed the containment he then notified ES&H Environmental and LA Tank. Stain's Roustabout Crew was called out in the event their services were needed. Mr. Gary then called the Gulfport Production Supervisor, Harry Schwartz to inform him of the incident and then called the NRC. He then called the SERC and spoke to Shelly. Shelly told Mr. Gary that she would make all necessary calls from that point. The USCG called the Hackberry Office and told Mr. Gary that it wasn't necessary for them to come but requested a copy of the invoice from ES&H Spill Response in order to verify the clean-up was performed by licensed professionals with proper equipment. ES&H completed the clean-up on April 4th at approximately 10:30 A.M.

X/Y:
Feet

1365100




1365100

GULFPORT ENERGY

Erwin Heirs Lease

Hackberry, Louisiana

Base Map





2004 8 9

